


# F OVERALL ELECTRICAL WIRING DIAGRAM

12 HIACE



Power Source



Turn Signal and Hazard Warning Light (RHD)



Horn (RHD)

